



\*\*\*\* = CN1/CN2/CN3 - 1  
 ☐☐☐☐☐ = CN1/CN2/CN3 - 2  
 +++ = ROI X2 - 8 / CN4 - 1

The connections V-c are the temperatures and are explained in the sheet "signals"

Author = Daniele Bortoli		
Title <b>GASCOD NG4</b>		
Size A3	Document Number <b>Power Supply Relays</b>	Rev 1.2.0
Date: Friday, March 01, 2013	Sheet 1	of 1