



This is the wiring for the use of 6 motors. If you don't want to use the double filter wheel you can ignore the connections JP4x with x = b to h, AMS1-1\_Y11 and ROI - X1-4